





L'OF
PROFES






Via Cimara 2 - 24046 Osio Sotto (bg) ITALY Tel. +39.035.808121 Fax. +39.035.078127 Email info@dawa.it export@dawa.it

NANO TOURMALINE TECHNOLOGY

UNISEX MINI STRAIGHTENER

Most compact hair straightener with 1.5 cm in length.
Worldwide Voltage (240/220/110 V).
Ceramic Tourmaline Heating Technology provide Negative Ions.
Fast heating element - Superior heat recovery time.
Eliminated frizz hair, Give shine.













[illegible]**baltur**

baltur

baltur



ona 30°

- ① Cotone 30°
- ② Sintetici 30°
- ③ Colorati
- ④ Delicati
- ⑤ Rapido 30°


Tradizionali

- 6 Cotone
- 7 Sintetici
- 8 Colorati
- 9 Eco 40°C
- 10 Bianco

Speciale

- 11
- 12
- 13
- 14
- 15
- 16

Push & Go



 **INDESIT**



Infinity

Zona 30°

- ❶ Cotone 30°
- ❷ Sintetici 30°
- ❸ Colorati
- ❹ Delicati
- ❺ Rapido 30'

Tradizionali

- ❻ Cotone
- ❼ Sintetici
- ❽ Misti
- ❾ Eco 40-60
- ❿ Bianchi


Speciali

- ⓫ Rapido --- ⌚
- ⓬ Piumini
- ⓭ Lana ⌘
- ⓮ 20°C
- ⓯ Risciacquo+Centrifuga
- ⓰ Centrifuga+Scarico

 **INDESIT**

Push & Go
Cotone e Sintetici 30° in 45 min

ON
OFF



AVVIO
PAUSA



 InverterMotor | **Inne**



Tradizionali

- 6 Cotone
- 7 Sintetici
- 8 Misti
- 9 Eco 40-60
- 10 Bianchi

Speciali

- 11 Rapido
- 12 Piumini
- 13 Lana
- 14 20°C
- 15 Risciacquo+Centrifuga
- 16 Centrifuga+Scarico

Push & Go
Cotone e Sintetici 30' in 45 min



10kg | 1400^{cc}



InverterMotor | **Innex**



IMPORTANTE
REGISTRATI IL TUO PRODOTTO PER
10 ANNI DI SERVIZI DI RIPARAZIONE CON RICAMBI GRATIS
800 729 141



Electrolux

TE1120

IMPORTANT
On a result of the improper frequency of the
blinking warning, the following blinking warn-
ings appear on the display:

EFO filter abnormally dirty
Consulting the warning:
1. Turn appliance ON. Appliance must be on.
2. Clean the filter (see user manual).
3. Put the filter back into the filter socket.
Drying with the blinking warning is
possible but activates overheating protection
and significantly increases the cycle time.
Drying performance cannot be guaranteed.

E10 stopped filter
Consulting the warning:
1. Turn appliance ON. Appliance must be on.
2. Clean the filter (see user manual).
3. Put the filter back into the filter socket.
Drying with the blinking warning is
not possible.

817805102.4-42118

Electrolux



IMPORTANT
Due to the frequency of the
blinking warning, the following
warning must be observed on the display:

EFO filter abnormally dirty

Consulting the warning:
1. Turn appliance ON. Appliance must be on.
2. Clean the filter (see user manual).
3. Put the filter back into the filter socket.
Drying with the blinking warning is
possible but activates overheating protection
and significantly increases the cycle time.
Drying performance cannot be guaranteed.

E10 clogged filter

Consulting the warning:
1. Turn appliance ON. Appliance must be on.
2. Clean the filter (see user manual).
3. Put the filter back into the filter socket.
Drying with the blinking warning is
not possible.

Electrolux







